

**Federal Aviation
Administration**

Transmittal Letter 22-11

APRIL 1, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5/19/2022	IL	Benton	Benton Muni	2/6538	3/21/2022	RNAV (GPS) RWY 18, Orig-C

AIRAC Date: 19 MAY 2022

FDC 2/6538 H96 IAP BENTON MUNI, BENTON, IL. RNAV (GPS) RWY 18, ORIG-C... CHART PROFILE NOTE:
VGSI AND DESCENT ANGLES NOT COINCIDENT (VGSI ANGLE {3.33}/TCH {44.6}). THIS IS RNAV (GPS) RWY
18, ORIG-D. 2203182042-PERM