

**FEDERAL AVIATION ADMINISTRATION  
FLIGHT STANDARDS SERVICE  
TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)  
TITLE 14 CFR PART 97.37**

Bearings, headings, courses, tracks and radials are magnetic. Elevations and altitudes are in feet, MSL. Altitudes are minimum altitudes unless otherwise indicated.  
Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

<u>AIRPORT</u>	<u>AIRPORT ID</u>	<u>CITY</u>	<u>STATE</u>	<u>AMDT NO</u>	<u>ACTUAL EFFECTIVE DATE</u>
LINDEN	KLDJ	LINDEN	NJ	3	22 APRIL 2021

**TAKEOFF MINIMUMS:**  
NA - OBSTACLES

**TEXTUAL DEPARTURE PROCEDURES:**

**VISUAL CLIMB OVER AIRPORT:**

**TAKEOFF OBSTACLE NOTES:**

**CONTROLLING OBSTACLES:**

**REMARKS:**

**FLIGHT INSPECTED BY**

PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJF-10) MEMO, APRIL 29, 2020  
SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.

**OFFICE** **DATE**

*Digitally signed by*

**JON DENTON**

Dec 29, 2020

**DEVELOPED BY**

JON DENTON (CASEY HILL)

*Digitally signed by*

**JON DENTON**

Dec 29, 2020

**OFFICE** **DATE**

AJV-A432

12/10/2020

**APPROVED BY**

LONNIE EVERHART

*Digitally signed by*

**JON DENTON**

Dec 29, 2020

**OFFICE** **DATE**

AJV-A430

**TITLE**  
MANAGER

**REQUIRED EFFECTIVE DATE:**

ROUTINE

**COORDINATED WITH:**

**A4A** ☐ **ALPA** ☒ **AOPA** ☒ **APA** ☒ **HAI** ☐ **NBAA** ☒ **OTHER:** AMGR, ZNY, NY TRACON, NJ DEP OF AVIATION

**CHANGES - REASONS:**

1. UPDATED TAKEOFF MINIMUMS TO "NA - OBSTACLES" AND REMOVED TAKEOFF OBSTACLES- EXCESSIVE CLIMB GRADIENTS AND VISIBILITY REQUIRED, AIRPORT FAILED FLIGHT INSPECTION DUE TO NON COMPLIANCE.

