

**Federal Aviation
Administration**

Transmittal Letter 19-02

November 30, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3-Jan-19	GA	Vidalia	Vidalia Rgnl	8/3626	11/15/18	ILS OR LOC RWY 25, Amdt 2

AIRAC Date: 3 JANUARY 2019

FDC **8/3626** VDI IAP VIDALIA RGNL, Vidalia, GA. ILS OR LOC RWY 25, AMDT 2...
CHANGE PLANVIEW ALTERNATE MISSED APPROACH COURSE INBOUND FROM
152.00 TO 155.00. THIS IS ILS OR LOC RWY 25, AMDT 2A. 1811082210-PERM