

**Federal Aviation  
Administration**

**Transmittal Letter 18-07**

**February 9, 2018**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY       | AIRPORT       | FDC<br>NUMBE | FDC<br>DATE | SUBJECT                         |
|---------------|-------|------------|---------------|--------------|-------------|---------------------------------|
| 29-Mar-18     | WA    | Moses Lake | Grant Co Intl | 7/5203       | 1/30/18     | ILS OR LOC RWY 32R, Amdt<br>20C |

**AIRAC Date: 29 MARCH 2018**

FDC **7/5203** MWH IAP GRANT CO INTL, Moses Lake, WA. ILS OR LOC RWY 32R,  
AMDT 20C... CHART NOTE: ASTERISK RVR 1800 AUTHORIZED WITH USE OF FD OR  
AP OR HUD TO DA, NA WHEN USING EPHRATA ALTIMETER SETTING. CHANGE S-  
ILS-32R TO S-ILS 32R ASTERISK. THIS IS ILS OR LOC RWY 32R, AMDT 20D.  
1710161410-PERM