

**Federal Aviation  
Administration**

**Transmittal Letter 22-20**

**August 5, 2022**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/8/2022	IL	Chicago/Au rora	Aurora Muni	2/9925	7/20/2022	LOC RWY 33, Amdt 1

**AIRAC Date: 8 SEPTEMBER 2022**

FDC 2/9925 ARR IAP AURORA MUNI, CHICAGO/AURORA, IL. LOC RWY 33, AMDT 1...  
EPABE FIX MINIMUMS: CIRCLING CAT C MDA 1300/HAA 588. THIS IS LOC RWY 33, AMDT  
1A. 2204191908-PERM