

**Federal Aviation  
Administration**

**Transmittal Letter 17-22**

**September 8, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12-Oct-17	AK	Ruby	Ruby	7/0492	8/29/17	RNAV (GPS) RWY 3, Amdt 1A

**AIRAC Date: 12 OCTOBER 2017**

**FDC 7/0492 RBY IAP RUBY, Ruby, AK. RNAV (GPS) RWY 3, AMDT 1A... CHART  
PROFILE NOTE: VISUAL SEGMENT - OBSTACLES. DELETE PROFILE NOTE:  
DESCENT ANGLE NA. THIS IS RNAV (GPS) RWY 3, AMDT 1B. 1707131533-PERM**