

**Federal Aviation
Administration**

Transmittal Letter 22-06

JANUARY 21, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2/24/2022	GA	Atlanta	Hartsfield - Jackson Atlanta Intl	2/1922	1/7/2022	ILS OR LOC RWY 10, Amdt 5

AIRAC Date: 24 FEBRUARY 2022

FDC 2/1922 ATL IAP HARTSFIELD - JACKSON ATLANTA INTL, ATLANTA, GA. ILS OR LOC RWY 10, AMDT 5...
CHART NOTE: SIMULTANEOUS APPROACH AUTHORIZED WITH RWY 9L OR 8R OR 8L OR RWYS 9L AND
8L. DISREGARD NOTE: SIMULTANEOUS APPROACH AUTHORIZED. PROCEDURE NOT AUTHORIZED
WHEN GLIDE SLOPE NOT AVAILABLE (ILS PROCEDURES ONLY). DUAL VHF COMM REQUIRED. SEE
ADDITIONAL REQUIREMENTS ON AAUP. THIS IS ILS OR LOC RWY 10, AMDT 5A. 2201071410-PERM