

**Federal Aviation
Administration**

Transmittal Letter 16-16

June 17, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
21-Jul-16	MA	New Bedford	New Bedford Rgnl	6/5461	6/6/16	ILS OR LOC RWY 5, Amdt 26

AIRAC Date: 21 JULY 2016

FDC 6/5461 EWB IAP NEW BEDFORD RGNL, NEW BEDFORD, MA. ILS OR LOC RWY 5, AMDT 26... CHANGE: ALL REFERENCES OF PROVIDENCE (PVD) VORTAC TO PROVIDENCE (PVD) VOR/DME. THIS IS ILS OR LOC RWY 5, AMDT 26A. 1606031828-PERM