

**Federal Aviation
Administration**

Transmittal Letter 22-24

September 30, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/3/2022	CO	Montrose	Montrose Rgnl	2/7519	9/19/2022	RNAV (GPS) RWY 35, Orig-D

AIRAC Date: 3 NOVEMBER 2022

FDC 2/7519 MTJ IAP MONTROSE RGNL, MONTROSE, CO. RNAV (GPS) RWY 35, ORIG-D... CHANGE NOTE TO READ: RWY 35 HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHANGE PLANVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVAL ON MTJ VOR/DME AIRWAY RADIALS 082 CW 257. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVAL ON ETL VOR/DME AIRWAY RADIALS 019 CW 143. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT NADIN ON V244 WESTBOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT MEYRS ON V26-244 EASTBOUND. THIS IS RNAV (GPS) RWY 35, ORIG-E. 2209141937-PERM