FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP) TITLE 14 CFR PART 97.37

Bearings, headings, courses, tracks and radials are magnetic. Elevations and altitudes are in feet, MSL Altitudes are minimum altitudes unless otherwise indicated

OFFICE

DATE

Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.								
AIRPORT	AIRPORT ID	CITY	STATE	AMDT NO	ACTUAL EFFECTIVE DATE			
MARION-CRITTENDEN CO JAMES C	K5M9	MARION	KY	1A	31 DECEMBER 2020			

TAKEOFF MINIMUMS:

RWY 7: STANDARD.

RWY 25: 300-1 1/2 OR STANDARD WITH MINIMUM CLIMB OF 215 FT PER NM TO 900.

TEXTUAL DEPARTURE PROCEDURES:

VISUAL CLIMB OVER AIRPORT:

TAKEOFF OBSTACLE NOTES:

NOTE: RWY 7: TREES BEGINNING 64 FT FROM DER, 281 FT LEFT OF CENTERLINE, UP TO 89 FT AGL/716 FT MSL. FENCE POST 93 FT FROM DER, 248 FT LEFT OF CENTERLINE, 6 FT AGL 1632 FT MSL. TREES BEGINNING 2656 FT FROM DER, LEFT AND RIGHT OF CENTERLINE, UP TO 100 FT AGL/749 FT MSL.

NOTE: RWY 25: TREES BEGINNING 123 FT FROM DER, 314 FT RIGHT OF CENTERLINE, UP TO 52 FT AGL/701 FT MSL. TREES BEGINNING 291 FT FROM DER, 303 FT LEFT OF CENTERLINE, UP TO 62 FT AGL/711 FT MSL. POLE 1150 FT FROM DER, 331 FT LEFT OF CENTERLINE, 35 FT AGL/686 FT MSL. TREES BEGINNING 2034 FT FROM DER, LEFT AND RIGHT OF CENTERLINE, UP TO 100 FT AGL/819 FT MSL.

CONTROLLING OBSTACLES:

FLIGHT INSPECTED BY

RWY 25: 819 FT MSL TREE 371955.71N/0880819.67W (CG, CEILING), 819 FT MSL TREE 371952.23N/0880824.48W (CGTA, VISIBILITY).

REMARKS:

PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJF-10) MEMO, APRIL 29, 2020, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.							
	Digitally signed by						
DEVELOPED BY	DONALD H LANIER	<u>OFFICE</u>	DATE				
DON LANIER (TAYLOR GIBSON)	Sep 28, 2020	AJV-A431	07/01/2020				
	Digitally signed by						
APPROVED BY	DONALD H LANIER	<u>OFFICE</u>	<u>DATE</u>	<u>TITLE</u>			
LONNIE EVERHART	Sep 28, 2020	AJV-A430		MANAGER			
	Digitally signed by						

COORDINATED WITH:

A4A ALPA AOPA AOPA APA HAI NBAA OTHER:ZME, AMGR

Sep 28, 2020

REQUIRED EFFECTIVE DATE: ROUTINE DONALD H LANIER

CHANGES - REASONS:

1. CHANGED AIRPORT NAME FROM "MARION-CRITTENDON COUNTY" TO "MARION-CRITTENDEN CO JAMES C JOHNSON RGNL" - PER KY DOT. 2. IDENTIFIED CEILING AND VISIBILITY OBSTACLES IN "CONTROLLING OBSTACLES" FOR RWY 25 - OBSTACLES IDENTIFIED IN S FILE. DOCUMENTED IAW 8260.46G, APPENDIX D, SECTION 1, PARAGRAPH 11A.

