## Federal Aviation Administration

**Transmittal Letter 18-21** 

### August 24, 2018

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

#### The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
11-Oct-18	OK	Madill	Madill Muni	8/7792	8/10/18	RNAV (GPS) RWY 18, Orig

# AIRAC Date: 11 OCTOBER 2018

FDC **8/7792** 1F4 IAP MADILL MUNI, Madill, OK. RNAV (GPS) RWY 18, ORIG... DELETE NOTE: GPS OR RNP-0.3 REQUIRED. DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. CHART NOTE: PROCEDURE NA AT NIGHT. NOTE: 34:1 IS NOT CLEAR. CHART NOTE: RWY 18, HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 18, ORIG-A. 1807181724-PERM