### Federal Aviation Administration

## **Transmittal Letter 22-04**

### December 24, 2021

### PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

#### The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: EFFECTIVEUPONPUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1/27/2022	ОН	Tiffin	Seneca County	1/7269	12/13/2021	RNAV (GPS) RWY 24, Amdt 1C

# AIRAC Date: 27 JANUARY 2022

FDC 1/7269 16G IAP SENECA COUNTY, TIFFIN, OH. RNAV (GPS) RWY 24, AMDT 1C... CIRCLING CAT C MDA 1340/HAA 554. CHANGE NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE FINDLAY ALTIMETER SETTING AND INCREASE ALL DA/MDA 60 FEET, AND INCREASE LPV, LNAV/VNAV ALL CATS VISIBILITY 1/8 SM, INCREASE LNAV AND CIRCLING CAT C VISIBILITY 1/4 MILE. THIS IS RNAV (GPS) RWY 24, AMDT 1D. 2112062209-PERM