

**Federal Aviation
Administration**

Transmittal Letter 22-20

August 5, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/8/2022	NJ	Trenton	Trenton Mercer	2/9704	7/20/2022	ILS OR LOC RWY 6, Amdt 10E

AIRAC Date: 8 SEPTEMBER 2022

FDC 2/9704 TTN IAP TRENTON MERCER, TRENTON, NJ. ILS OR LOC RWY 6, AMDT 10E...
CIRCLING CAT C MDA 840/HAA 627. EMUNY FIX MINIMUMS: CIRCLING CAT C MDA
760/HAA 547, CAT D MDA 960/HAA 747, VISIBILITY CAT D 2 1/2. DELETE NOTE: * LOC
ONLY. DELETE ASTERISK FROM MINIMUM ALTITUDE AT EMUNY IN 840. THIS IS ILS OR
LOC RWY 6, AMDT 10F. 2205051747-PERM