

**Federal Aviation
Administration**

Transmittal Letter 08-14

May 30, 2008

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
05/22/08	TX	San Angelo	San Angelo Regional/Mathis Fld	8/8790		VOR/DME OR TACAN RWY 3, ORIG

AIRAC Date: 22 MAY 2008

FDC 8/8790 SJT FI/P SAN ANGELO REGIONAL/MATHIS FLD, SAN ANGELO, TX.
VOR/DME OR TACAN RWY 3, ORIG...DELETE PLANVIEW NOTE: RADAR
REQUIRED. THIS IS VOR/DME OR TACAN RWY 3, ORIG-A.