

**Federal Aviation
Administration**

Transmittal Letter 20-21

August 21, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/8/2020	NE	Ainsworth	Ainsworth Rgnl	0/2205	8/14/2020	VOR RWY 35, Amdt 4A

AIRAC Date: 8 OCTOBER 2020

FDC 0/2205 ANW IAP AINSWORTH RGNL, AINSWORTH, NE. VOR RWY 35, AMDT 4A...
CHART CIRCLING ICON. BIYAG FIX MINIMUMS, CIRCLING CAT D MDA 3200/HAA 611. THIS
IS VOR RWY 35, AMDT 4B. 2008131607-PERM