

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
 .....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-May-13	VA	Richmond	Richmond Intl	3/4790	03/25/13	VOR RWY 34, Amdt 23A

FDC **3/4790** RIC FI/P IAP RICHMOND INTL, RICHMOND, VA. VOR RWY 34, AMDT 23A... CHANGE MISSED APPROACH POINT TO READ: 5.25 MILES AFTER LUCAR OR AT RIC 0.75 DME; VDP AT RIC VORTAC 1.7 DME. DISTANCE VDP TO RW34 1.0 NM. THIS IS VOR RWY 34, AMDT 23B