

HOT SPOTS

An "Airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or ellipses designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

| CITY/AIRPORT | HOT SPOT | DESCRIPTION |
|--|----------|--|
| ARKANSAS | | |
| LITTLE ROCK BILL AND HILLARY CLINTON NTL/ADAMS FLD (LIT) | HS 1 | Wrong Rwy Departure Risk – Rwy 36 and Rwy 04L thlds in close proximity and share single hold lines at both Twy A7 and Twy F6. Ensure correct rwy alignment. |
| LOUISIANA | | |
| BATON ROUGE BATON ROUGE METRO, RYAN FLD (BTR) | HS 1 | Complex int Twy A, Twy B, Twy D and Twy K W of Rwy 13–31 and Rwy 04L–22R. |
| HOUMA HOUMA–TERREBONNE (HUM) | HS 1 | Rwy Incursion Risk: Complex intersection Twy H, Twy E and Twy B east of Rwy 18–36 & Rwy 12–30. |
| | HS 2 | Remain alert due to numerous copter ops |
| LAFAYETTE LAFAYETTE RGNL/PAUL FOURNET FLD (LFT) | HS 1 | Rwy incursion risk. Rwy 11–29, Rwy 04L–22R, Twy B, F, and J. Complex geometry due to converging Rwy and Twys. |
| | HS 2 | Risk of surface incident. Twys F, J, H, and K. Complex geometry due to converging Twys. |
| NEW ORLEANS LAKEFRONT (NEW) | HS 1 | Rwy Incursion Risk at Twy F and Rwy 09–27 – Wide intersection. |
| | HS 2 | Rwy Incursion Risk at Twy F and Rwy 27– Hold Line is at Apron exit on Twy F. |
| | HS 3 | Rwy Incursion Risk at Twy B and Rwy 36L– Apron exit east of Rwy 36L is inside Hold Lines. |
| NEW ORLEANS LOUIS ARMSTRONG NEW ORLEANS INTL (MSY) | HS 1 | Limited wingtip clearance on Twy G near Concourse Bravo due to acft pushbacks. Maint vigilance exiting Rwy 11/29 on Twy G8 and when taxiing on Twy G. High Traffic area. |
| | HS 2 | Green painted ovrn for Rwy 11–29 can be misinterpreted for Twy E when landing Rwy 02–20. |
| | HS 3 | Rwy 11–29 and Twy G6, hi No of rwy crossings. |
| MISSISSIPPI | | |
| COLUMBUS COLUMBUS AFB (CBM) | HS 1 | Maint vigilance numerous twys in area of Rwy 13R. |
| | HS 2 | Rwy incursion risk for Rwy 13R/31L, Twy M. |
| | HS 3 | Rwy incursion risk for Rwy 13R/31L, Twy J, Twy E. |
| OKLAHOMA | | |
| ALTUS ALTUS AFB (LTS) | HS 1 | Acft taxiing on Twy B between Spot 47 and Twy D. |
| NORMAN UNIVERSITY OF OKLAHOMA WESTHEIMER (OUN) | HS 1 | Rwy 03–21 hold marking is in close proximity to the ramp. |
| | HS 2 | Rwy 03–21 hold marking is in close proximity to the ramp. |
| | HS 3 | Rwy 03–21 hold marking is a short taxi distance from Rwy 18–36. |
| | HS 4 | Pilots taxiing westbound on Twy B risk incursion of Rwy 18–36 if they miss the turn to Twy C. |

AIRPORT DIAGRAMS

527

| CITY/AIRPORT | HOT SPOT TEXAS | DESCRIPTION |
|---|-------------------|---|
| AUSTIN AUSTIN-BERGSTROM INTL (AUS) | HS 1 | Drivers northbound on E svc road may be unaware of acft from Rwy 36R exiting at Twy G and Twy H. |
| | HS 2 | Risk of surface incident. Acft exiting Rwy 36R on Twy G sometimes turn onto Twy H thinking it is a continuation of Twy G. |
| AUSTIN SAN MARCOS RGNL (HYI) | HS 1 | Rwy incursion/wrong rwy departure risk. Ensure correct rwy alignment. Complex airfield geometry at rwy/rwy int. |
| | HS 2 | Rwy incursion/wrong rwy departure risk. Ensure correct rwy alignment. Complex airfield geometry. Rwy thlds in close proximity. |
| BEAUMONT/PORT ARTHUR JACK BROOKS RGNL (BPT) COLLEGE STATION EASTERWOOD FLD (CLL) | HS 1 | South end of Twy B not visible from ctl twr. |
| | HS 1 | Rwy holding posn markings non typical lctn. Pilots sometime incorrectly cross the holding posn markings on Twy B when taxied to Rwy 11. |
| DALLAS ADDISON (ADS) | HS 1 | Twy A and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 2 | Twy J and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 3 | Twy H and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 4 | Twy G and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 5 | Twy F and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 6 | Twy E and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 7 | Twy D and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 8 | Twy C and Rwy 16-34. Holding Position Markings have been moved back to the edge of Twy A. |
| | HS 9 | Twy A and Rwy End 34. Holding Position Markings have been moved back to the edge of Twy A prior to turn off parallel twy. |
| EL PASO EL PASO INTL (ELP) | HS 1 | Rwy 08R apch considered acft, do not proceed on or cross w/o ATC clnc especially when taxiing to Rwy 04 via the terminal ramp. |
| GEORGETOWN GEORGETOWN EXEC (GTU) | HS 1 | Acft taxiing on Twy A should exp to giveaway to acft exiting Rwy 18-36 at Twy J. |
| | HS 2 | Acft taxiing on Twy A should exp to giveaway to acft exiting Rwy 18-36 at Twy D. |
| HARLINGEN VALLEY INTL (HRL) | HS 1 | Southeast corner of the airport and coincident thlds of Rwy 31 and Rwy 36R may cause confusion for departing acft. |
| HOUSTON CONROE/NORTH HOUSTON RGNL (CXO) | HS 1 | Twy F west of Twy D not visible from ctl twr. |

| CITY/AIRPORT | HOT SPOT | DESCRIPTION |
|--|----------|--|
| HOUSTON DAVID WAYNE HOOKS MEML (DWH) | HS 1 | Rwy Incursion Risk– Ramp accessible to inadequately trained drivers; inadequate signage leaving ramp. |
| | HS 2 | Rwy Incursion Risk– Complex twy intersection near Rwy 17L. |
| | HS 3 | Rwy Incursion Risk– Previous Incursions occurring Twy E at Rwy 17R–35L. |
| | HS 4 | Rwy Incursion Risk – Int of Twy G and Rwy 17L–35R. Acft exiting Rwy 17R–35L at Twy G sometimes fail to turn onto Twy F and enter Rwy 17L–35R wo a clnc. |
| | HS 5 | Rwy Incursion Risk – Int of Twy H and Rwy 17L–35R. Acft exiting Rwy 17R–35L at Twy H sometimes fail to turn onto Twy F and enter Rwy 17L–35R wo a clnc. |
| | HS 6 | Rwy Incursion Risk – Incursions occurring on Twy K at Rwy 17L. |
| HOUSTON SUGAR LAND RGNL (SGR) | HS 1 | Twy E int with Twy A and Twy A3 incr likelihood of conflicts btn acft due to short dist fr Rwy 17–35. |
| HOUSTON WILLIAM P HOBBY (HOU) | HS 1 | Rwy Incursion Risk– Twy G at Rwy 13R: Numerous incursions, pilots inadvertently miss Hold Lines on Twy G at Rwy 13R. |
| | HS 2 | Rwy Incursion Risk. Twy E crosses Rwy 13L approach. Runway Holding Position Markings are crossed inadvertently. |
| MC ALLEN MC ALLEN INTL (MFE) | HS 1 | Rwy 14 hold short marking lctd on Twy A is perpendicular to Rwy 14. |
| MIDLAND MIDLAND INTL AIR AND SPACE PORT (MAF) | HS 1 | Rwy Incursion Risk: northbound pilots inadvertently miss turn onto Twy A on Twy P and incur Rwy 10–28. Confusing intersection: Twy B and Twy P converge on Rwy 10–28. |
| | HS 2 | Area not visible from twr. Limited air tfc services provided. |
| NEW BRAUNFELS NEW BRAUNFELS NTL (BAZ) | HS 1 | Wrong Rwy Departure Risk – Rwy 13 intersection Twy D and Rwy 17 threshold in close proximity. Ensure correct rwy alignment. Rwy 13 and Rwy 17 share the same hold short line at Twy D. |
| SAN ANGELO SAN ANGELO RGNL/MATHIS FLD (SJT) | HS 1 | Rwy 18–36 at the int of Rwy 09–27 is a hi energy areas where extra caution is nec dur rwy crossings. |
| | HS 2 | Rwy 18–36 at the int of Twy D is a hi energy areas where extra caution is nec dur rwy crossings. |
| | HS 3 | Rwy 03 Hold Short Line is a Hot Spot where acft are required to hold when req a Rwy 36 Departure and ops are being conducted on Rwy 03–21. |
| SAN ANTONIO KELLY FLD (SKF) | HS 1 | The unpaved portion of the north overrun. |
| | HS 2 | Int of Rwy 16–34, Twy D, and Twy G. |
| SAN ANTONIO SAN ANTONIO INTL (SAT) | HS 1 | Rwy 04 at Rwy 31L. Acft taxiing on Rwy 04 sometimes fail to hold short of Rwy 31L. |
| | HS 2 | Twy G and Twy N in close proximity of Rwy 31L. Acft taxiing northbound on Twy N sometimes fail to make the turn onto Twy G and enter Rwy 31L without approval. |
| TYLER TYLER POUNDS RGNL (TYR) | HS 1 | Rwy Incursion Risk: Complex int Twy K, Twy K2 leads to the approach end of 2 Rwy's, Rwy 18–36, and Rwy 13–31. |
| WACO WACO RGNL (ACT) | HS 1 | Rwy 01 hold short line at approach end not visible from the tower. |

AIRPORT DIAGRAMS

529

| CITY/AIRPORT | HOT SPOT | DESCRIPTION |
|---------------------------------------|----------|--|
| WICHITA FALLS | | |
| SHEPPARD AFB/WICHITA FALLS MUNI (SPS) | HS 1 | Rwy 18-36 and Twy E. High number of vehicle traffic and crossings. |
| | HS 2 | Twy G and Rwy 15R-33L. High numbers of aircraft and vehicles crossing and entering runway. |
| | HS 3 | Twy G and Rwy 15C-33C. High numbers of aircraft and vehicles crossing and entering runway. |