

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Idg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

⚠

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH:

Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF) 1
------------------------	---	---------------------------------

ELEV 2706	TDZE 2706	6000 HAYNI VGSi and RNAV glidepath not coincident (VGSi Angle 3.00/TCH 25).			
		*LNAV only	*1.7 NM to RWY 30	IBOXE 5 NM Holding Pattern	GP 3.00° TCH 40
		RWY 30	KAKUH 4300	IBOXE 5000	
		1.7 NM	3.2 NM	6 NM	
CATEGORY		A	B	C	D
LPV DA		2956-1		250 (300-1)	
LNAV/VNAV DA		3233-1 7/8		527 (600-1 7/8)	
LNAV MDA		3260-1	554 (600-1)	3260-1 5/8	554 (600-1 5/8)
CIRCLING		3260-1	554 (600-1)	3260-1 5/8	3460-2 1/2 554 (600-1 5/8) 754 (800-2 1/2)

HETTINGER, NORTH DAKOTA

Amclt 1 26MAY16

46°01'N-102°39'W

HETTINGER/JB LINDQUIST RGNL (HEI)

RNAV (GPS) RWY 30