

ILS Z or LOC Z RWY 21
ROSWELL AIR CENTER (ROW)

MISSED APPROACH: Climb to 5000 then climbing right turn to 6000 on CME VORTAC R-195 to CME VORTAC and hold, continue climb-in-hold to 6000.

Diagram illustrating various navigation aids and procedures:

- Top Left:** A diagram showing a 5600 NPT to 116.3 CNM arc. A 17 CME is indicated. The (IAF) IPNUC CME 17 is also shown.
- Top Right:** A circular inset showing a 360-degree bearing from a station to a point labeled 5400. The bearing is 360°.
- Middle Left:** A diagram showing a 5000 to 6000 CME R-195 arc. A 17 CME is indicated.
- Middle Right:** A diagram showing a 5018 RO LOM TOPAN I-ROW 7 station. A 17 CME is indicated.
- Bottom Left:** A diagram showing a 5018 station. A 1.1 NM distance is indicated. A 3.5 NM distance is also indicated.
- Bottom Right:** A diagram showing a 5018 station. A 1.1 NM distance is indicated. A 3.5 NM distance is also indicated.
- Bottom Center:** A table with columns for CATEGORY, A, B, C, and D.

ROSWELL AIR CENTER (ROW)
ILS Z or LOC Z RWY 21

SW-1, 04 SEP 2025 to 02 OCT 2025