



ILS RWY 11 (CAT II & III)
WORCESTER RGNL (ORH)

MISSED APPROACH: Climb to 1800 then climbing right turn to 3100 on heading 230° and on GDM VOR/DME R-167 to LAWRN/GDM 23 DME and hold, continue climb-in-hold to 3100.

UNICOM

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

NE-1, 04 SEP 2025 to 02 OCT 2025