

WAAS
CH **97701**
W10A

APP CRS
100°

Rwy Ldg
TDZE
857
Apt Elev
868

RNAV (GPS) RWY 10

FAIRFIELD COUNTY (LHQ)

RNP APCH - GPS.

▼

Rwy 10 helicopter visibility reduction below ¾ SM NA. When local altimeter setting not received, use Rickenbacker Intl altimeter setting and increase all MDAs 60 feet and LNAV visibility Cat C ¼ SM, and Circling visibility Cat C ¼ SM. When Circling Rwy 28 at night, operational VGSI required, remain on or above VGSI glidepath until threshold.

▲

MISSED APPROACH:
Climb to 2800 direct
DIPAC and hold.

ASOS 118.375	COLUMBUS APP CON 134.0 279.6	CLNC DEL 121.65	UNICOM 122.725 (CTAF) 0
------------------------	--	---------------------------	-----------------------------------

ELEV 868 TDZE 857

100°

5003 X 75

82

4 NM Holding Pattern

6000
2700

280°
100°

HASPI

100°

BERAY

2600

3.00°
TCH 40

1720

GAGSE 2.6 NM to RW10

RW10

2800

DIPAC

CATEGORY	A	B	C	D
LP MDA	1300-1	443 (500-1)	1300-1½ 443 (500-1½)	NA
LNAV MDA	1440-1	583 (600-1)	1440-1¾ 583 (600-1¾)	NA
CIRCLING	1500-1 632 (700-1)	1540-1 672 (700-1)	1620-2¼ 752 (800-2¼)	NA

LANCASTER, OHIO

FAIRFIELD COUNTY (LHQ)

Amtd 1 21MAR24

39°45'N-82°39'W

RNAV (GPS) RWY 10