

WAAS CH 45635 W33A	APP CRS 330°	Rwy Ldg TDZE 7926 Apt Elev 7950
--	------------------------	---

RNAV (GPS) RWY 33

CENTRAL COLORADO RGNL (A.E.J)

NA

-21°C

Circling NA northeast of Rwy 15-33. DME/DME RNP-0.3 NA.

When local altimeter setting not received, use Salida altimeter setting and increase all MDA 100 feet. VDP NA with Salida altimeter setting.

#Missed approach requires minimum climb of 425 feet per NM to 14100.

MISSED APPROACH: Climbing right turn to 16000 direct KANON and hold, continue climb-in-hold to 16000.

AWOS-3 132.925	DENVER CENTER 119.85 363.15	UNICOM 122.8 (CTAF) 0
--------------------------	---------------------------------------	---------------------------------

ELEV 7950		TDZE 7926				
MIRL Rwy 15-33 330°		16000 KANON VGSI and descent angles not coincident (VGSI Angle 3.00/TCH 41). BUBYO				
*LNAV only. ROBYV AKNAC 10300 330° 3.44° TCH 41 1.3 1.8 NM 3.4 NM 7.7 NM		*1.8 NM to ROBYV 338° 12600				
CATEGORY	A	B	C	D		
#LP	MDA	8960-1½	1034 (1100-1½)	8960-3	1034 (1100-3)	NA
LP	MDA	9840-1½	1914 (1900-1½)	9840-3	1914 (1900-3)	NA
#LNAV	MDA	9300-1½	1374 (1400-1½)	9300-3	1374 (1400-3)	NA
LNAV	MDA	9980-1½	2054 (2100-1½)	9980-3	2054 (2100-3)	NA
CIRCLING		9980-1½	2030 (2100-1½)	9980-3	2030 (2100-3)	NA

BUENA VISTA, COLORADO

Orig-B 31MAR16

38°49'N-106°07'W

CENTRAL COLORADO RGNL (A.E.J)

RNAV (GPS) RWY 33