


TRYBE FOUR ARRIVAL (RNAV)

CLEVELAND, OHIO



NOTE: RADAR required.

NOTE: RNAV 1.

NOTE: DME/DME/IRU or GPS required.

NOTE: Jet aircraft expect "descend via"

clearance from Cleveland Center.

NOTE: Jet aircraft descend via MACH number

until intercepting 280K. Maintain 280K

until slowed by the STAR.

(NARRATIVE ON FOLLOWING PAGE)

NOTE: Chart not to scale.