

ILS or LOC RWY 4L
BILL AND HILLARY CLINTON NTL/ADAMS FLD (LIT)

MALSR

MISSED APPROACH: Climb to 1500 then climbing left turn to 3500 on heading 260° and on LIT VORTAC R-303 to ROLAN INT/LIT 16.7 DME and hold.

MIRL Rwy 18-36
 HIRL Rwy 4R-22L and 4L-22R
 TDZ/CL Rwy 22R

FAF to MAP 4.7 NM					
Knots	60	90	120	150	180
Min:Sec	4:42	3:08	2:21	1:53	1:34

LOM LASKY INT

Remain within 10 NM

227°

2100

047°

GS 3.00° TCH 51

1900

1814

I-LIT 4.5

JIRUR INT I-LIT 1.8

I-LIT 1.1

I-LIT 0.2

1500

3500

hdg 260°

LIT R-303

ROLAN △

960

2.7 NM

0.7 NM

1.3 NM

Use I-LIT DME when on the localizer course.

CATEGORY	A	B	C	D
S-ILS 4L	508/40 250 (300-¾)			
S-LOC 4L	960/40	702 (700-¾)	960-1½	702 (700-1½)
CIRCLING	960-1 694 (700-1)	1000-1 734 (800-1)	1180-2¾ 914 (1000-2¼)	1180-3 914 (1000-3)
JIRUR FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED)				
S-LOC 4L	720/40	462 (500-¾)	720/50	462 (500-1)
CIRCLING	820-1 554 (600-1)	1000-1 734 (800-1)	1180-2¾ 914 (1000-2¼)	1180-3 914 (1000-3)