

ILS RWY 29(SA CAT I & II)
PORTLAND INTL JETPORT (PWM)

MALSR 	MISSED APPROACH: Climb to 700 then climbing left turn to 3000 direct ENE VOR/DME and hold.
--	---

KENNEBUNK
117.1 ENE
Chan 118

LOCALIZER 109.9
I-GCS
Chan 36

PEATT
I-GCS 4.9
RADAR

(IF/IAF)
SAPPE
I-GCS 10.6
RADAR 3000

NoPT at SAPPE for arrival on
CDOGG or SCOGS arrivals.

ELEV 76 TDZE 56

MSA ENE 25 NM
3600
3100
1900
145°
055°
235°

700 ↑	3000 ↖	ENE 				
CATEGORY	A	B	C	D		
S-ILS 29	SA CAT I	RA 206/14	150 DA 206			
S-ILS 29	SA CAT II	RA 146/12	100 DA 156			
SA CATEGORY I & II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED						

NE-1, 02 OCT 2025 to 30 OCT 2025