



ILS RWY 1 (CAT II)
RONALD REAGAN WASHINGTON NTL (DCA)

ALSF-2

MISSED APPROACH: Climb to 420 then climbing left turn to 2200 on DCA VOR/DME R-325 to GTN NDB/INT/DCA 5.9 DME and hold.

GND CON
121.7 257.6



CATEGORY II ILS- SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED