

VOR/DME or TACAN RWY 10

VORTAC SYA 109.0 Chan 27	APCH CRS 092°	Rwy Idg 10,004 TDZE 98 Arpt Elev 98
--------------------------------	------------------	---

[USAF]

EARECKSON AS (SYA) (PASY)


* When ALS inop, increase CAT AB vis to 1½ miles;
CAT CDE vis to 1¾ miles.
** Circling not authorized N of Rwy 10-28.



MISSED APPROACH: Climb to 1200, then climbing right turn to 4200, intercept SYA R-272 direct EMLAW and hold.

ANCHORAGE CENTER 119.1 339.8	CTAF 127.2 352.05
---------------------------------	----------------------

CAUTION: Numerous obstructions in area N of Rwy 10-28.
Missed approach requires use of RNAV or ATC RADAR monitoring.



					ELEV 98	TDZE 98
WEMS SYA 11	BOVJU SYA 5	SYA VORTAC	ELVEK SYA 0.3	SYA ELVEK SYA 0.1		
2500	1800	1200	4200	EMLAW R-272 16		
092°	2.56°	092°	020°	092°		
4.9 NM	1.2 NM					
CATEGORY	A	B	C	D	E	
S-10 *	640-1	542 (600-1)	640-1½	542 (600-1½)		
CIRCLING **	640-1½	542 (600-1½)	640-1¾	562 (600-2)	582 (600-2)	HIRL Rwy 10-28 REIL Rwy 10 and 28

VOR/DME or TACAN RWY 10

AK, 02 OCT 2025 to 27 NOV 2025

AK, 02 OCT 2025 to 27 NOV 2025