

VORTAC MHZ 113.2 Chan 79	APP CRS 349°	Rwy Idg 8500 TDZE 346 Apt Elev 346
--	------------------------	---

VOR/DME or TACAN RWY 34R
JACKSON-MEDGAR WILEY EVERS INTL (JAN)

T When local altimeter setting not received, use Hawkins Fld altimeter setting and increase all MDA 20 feet; increase S-34R Cats C/D/E visibility $\frac{1}{8}$ mile.
A Circling NA for Cat E southwest of Rwy 16R-34L. Helicopter visibility reduction below $\frac{3}{4}$ SM NA.
 ASR

MISSED APPROACH: Climbing right turn to 3000 on heading 120° and MHZ VORTAC R-134 to RAKIN INT/MHZ 16.5 DME and hold.

ATIS 121.05	JACKSON APP CON ★ 123.9 317.7	JACKSON TOWER ★ 120.9 (CTAF) 0 352.0	GND CON 121.7 348.6	UNICOM 122.95
----------------	----------------------------------	---	------------------------	------------------

