

VORTAC RQZ

112.2

Chan 59

APP CRS

010°

Rwy Idg

5500

TDZE

978

Apt Elev

984

VOR/DME RWY 2

FAYETTEVILLE MUNI (FYM)

▼

NA

When local altimeter setting not received, use Huntsville Exec Tom Sharp Jr Fld altimeter setting and increase all MDA 120 feet; increase S-2 Cat C/D visibility ¼ SM, Circling Cat C visibility ½ SM, and Circling Cat D visibility ¼ SM. Rwy 2 helicopter visibility reduction below ¾ SM NA.

MISSED APPROACH: Climb to 2000 then climbing left turn to 3000 via RQZ R-010 to JOYER INT and hold.

AWOS-3 135.275	HUNTSVILLE APP CON ★ 125.6 354.1	CLNC DEL (GCO) 121.725	UNICOM 122.8 (CTAF) 0
-------------------	-------------------------------------	---------------------------	--------------------------

RQZ VORTAC		VGSI and descent angles not coincident (VGSI 3.00/TCH 22).		2000	3000	JOYER RQZ 10.6
4000		3000		2600		RQZ 15.6
Procedure Turn NA		3.00° TCH 40		5.6 NM		5 NM
CATEGORY	A	B	C	D		
S-2	1400-1	422 (500-1)	1400-1½ 422 (500-1¼)	1400-1½ 422 (500-1½)		
CIRCLING	1420-1 436 (500-1)	1540-1 556 (600-1)	1580-1½ 596 (600-1½)	1580-2 596 (600-2)		

FAYETTEVILLE, TENNESSEE

Orig-H 07SEP23

35°04'N-86°34'W

FAYETTEVILLE MUNI (FYM)

VOR/DME RWY 2