

LOC I-LCK 110.1	APP CRS 232°	Rwy Idg 12103 10913	23L	23R
			TDZE	740 743
			Apt Elev	744 744


ILS or LOC RWY 23L
RICKENBACKER INTL (LCK)

⚠ Circling NA northwest of Rwy 5L-23R. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting: increase DA to 975 feet; increase all MDAs 40 feet and S-LOC 23L visibility Cats C/D to RVR 5500 and Circling visibility Cat D to 2¼ SM. Autopilot coupled approach N/A below 1000 MSL.



MALSR

MISSED APPROACH: Climb to 3000, then left turn direct XUB VOR and hold.

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------



ELEV 744	TDZE 23L 740
	TDZE 23R 743



CATEGORY	A	B	C	D
S-ILS 23L	940/24 200 (200-½)			
S-LOC 23L	1220/24 480 (500-½)	1220/50 480 (500-1)		
SIDESTEP RWY 23R	1220-1 477 (500-1)	1220-1½ 477 (500-½)	1220-2 477 (500-2)	
CIRCLING	1240-1 496 (500-1)	1280-1½ 536 (600-½)	1400-2 656 (700-2)	