

ILS or LOC RWY 3R
DETROIT METRO WAYNE COUNTY (DTW)

MISSED APPROACH: Climb to 1100 then climbing right turn to 4000 on DXO VOR/DME R-122 to GAAGE/DXO 16.1 DME and hold.

ELEV 645	D	TDZE 633
HIRL all runways		
REIL Rwy's 3L, 9L, 9R and 21R		
TDZ/CL Rwy's 3R, 4L, 4R and 22R		

