

ILS or LOC RWY 22

MISSED APPROACH: Climb to 1800 then climbing right turn to 3000 direct MLU VORTAC and hold, continue climb-in-hold to 3000.



1800 3000 MLU

BAYU OM MLU 5.1

VGS1 and ILS glidepath not coincident (VGS1 Angle 3.00/TCH 50)

Remain within 10 NM

042° 222° 2100

1675 1700

UTPEF MLU 1.8

560*

GS 3.00° TCH 54

*LOC only.

CATEGORY	A	B	C	D
S-ILS 22	278-½	200 (200-½)		
S-LOC 22	560-½ 482 (500-½)		560-1 482 (500-1)	
CIRCLING	580-1 501 (600-1)		740-1¾ 661 (700-1¾)	1160-3 1081 (1100-3)

UTPEF FIX MINIMUMS

CATEGORY	A	B	C	D
S-LOC 22	500-½ 422 (500-½)		500-¾ 422 (500-¾)	
CIRCLING	580-1 501 (600-1)		740-1¾ 661 (700-1¾)	1160-3 1081 (1100-3)

MONROE RGNL (MLU)
ILS or LOC RWY 22