

ILS RWY 29 (SA CAT I & II)
PORTLAND INTL JETPORT (PWM)

MISSED APPROACH:
Climb to 700 then
climbing left turn to
3000 direct ENE
VOR/DME and hold.

700 ↑	3000 ↖	ENE 	PEATT I-GCS <u>4.9</u> RADAR 1700		SAPPE I-GCS <u>10.6</u> RADAR 1700	One Minute Holding Pattern
CATEGORY	A	B	C	D		
S-ILS 29	SA CAT I	RA 206/14	150 DA 206			
S-ILS 29	SA CAT II	RA 146/12	100 DA 156			
SA CATEGORY I & II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED						

NE-1, 30 OCT 2025 to 27 NOV 2025