

APP CRS

306°

Rwy Ldg

7614

TDZE

57

Apt Elev

62

RNAV (RNP) Z RWY 30L

NORMAN Y MINETA SAN JOSE INTL (SJC)

RNP AR APCH.

For uncompensated Baro-VNAV systems, procedure NA below 1°C or above 54°C. For inop ALS, increase RNP 0.10 all Cats visibility to RVR 5500 and increase RNP 0.30 all Cats visibility to 1½ SM.

MALSR

AG

MISSED APPROACH: Climb to 2000 on track 306° to ARTAQ and hold.

D-ATIS 126.95	NORCAL APP CON 120.1 290.25	SAN JOSE TOWER★ 124.0 (CTAF) 0 257.6	GND CON 121.7	UNICOM 122.95
------------------	--------------------------------	---	------------------	------------------

ELEV 62

D

TDZE 57

REIL Rwy 12L

HIRL Rwy 12L-30R and 12R-30L

2000

tr 306°

ARTAQ

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 70).

See planview for multiple IF locations.

RW30L

306°

WOXAR

1600

GP 3.00°

TCH 54

CATEGORY	A	B	C	D
RNP 0.10 DA		430/35	373 (400-½)	
RNP 0.20 DA		464/40	407 (500-¾)	
RNP 0.30 DA		541/50	484 (500-1)	

AUTHORIZATION REQUIRED

SAN JOSE, CALIFORNIA

Amtd 4 02DEC21

NORMAN Y MINETA SAN JOSE INTL (SJC)

RNAV (RNP) Z RWY 30L

37°22'N-121°56'W