

LOC I-GJC <u>108.95</u>	APP CRS 052°	Rwy Ldg TDZE Apt Elev	7001 228 236
-----------------------------------	------------------------	-----------------------------	---

ILS or LOC RWY 5
COLUMBIA METRO (CAE)



RADAR required for procedure entry.

T For inop ALS, increase S-SLS 5 Cat E visibility to RVR 4000, increase S-LOC 5 Cats C/D/E visibility to 2 SM and increase IKUPY minimums S-LOC 5 Cats C/D/E visibility to RVR 5500.
*RVR 1800 authorized with use of FD or AP or HUD to DA.

MALSR

MISSED APPROACH: Climb to 1500 then climbing right turn to 2300 direct CAE VORTAC and hold, continue climb-in-hold to 2300. (TACAN aircraft continue on CAE VORTAC R-140 to ADCOM INT/CAE VORTAC 10 DME and hold NW, right turn, 140° inbound).

ATIS 120.15	COLUMBIA APP CON 124.15 338.2 (110°-289°) 133.4 285.6 (290°-109°)		COLUMBIA TOWER 119.5 257.8	GND CON 121.9 348.6
-----------------------	---	--	--------------------------------------	-------------------------------



COLUMBIA, SOUTH CAROLINA
Amdt 3A 12JUN25

33°56'N-81°07'W

COLUMBIA METRO (CAE)
ILS or LOC RWY 5

SE-2, 25 DEC 2025 to 22 JAN 2026

SE-2, 25 DEC 2025 to 22 JAN 2026