

ILS or LOC RWY 23R
PIEDMONT TRIAD INTL (GSO)

Simultaneous approach authorized.

MISSED APPROACH: Climb to 1500 then climbing right turn to 3100 on heading 015° and GSO VORTAC R-360 to MAYOS INT/GSO 16.9 DME and hold.

TDZ/CL Rwy 5L, 23R and 23L
REIL Rwy 32
HIRL Rwy 14-32, 5R-23L and 5L-23R

FAF to MAP 5.8 NM

1500 ↑	3100 hdg 015°	GSO R-360	MAYOS △	HEVED INT I-IDB 7.5	054°	Remain within 10 NM
VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 72).				2800	234°	3100
I-IDB 1.7				I-IDB 2.8	2800	GS 3.00% TCH 55
1.1 NM				4.7 NM		
CATEGORY	A		B	C	D	
S-ILS 23R	1064/18			200 (200-1/2)		
S-LOC 23R	1280/24 416 (400-1/2)			1280/40		416 (400-3/4)
CIRCLING	1440-1 514 (600-1)			1700-2 1/4 774 (800-2 1/4)		1700-2 1/2 774 (800-2 1/2)