

HI-VOR Z or TACAN Z RWY 30

VORTAC AKN 112.8 Chan 75	APCH CRS 296°	Rwy Idg 8501 TDZE 73 Arpt Elev 73
--	-------------------------	--


[USAF]

KING SALMON (AKN) (PAKN)

DME required.


MISSED APPROACH: Climbing left turn to 3000 on heading 240° and on AKN VORTAC R-210 to OLLER/15 DME and hold.

ATIS 128.8	ANCHORAGE CENTER 124.8 354.0	TOWER ★ 118.3 279.5	GND CON 121.9	CTAF 121.9 0 352.05	UNICOM 122.95
---------------	---------------------------------	------------------------	------------------	------------------------	------------------



EMERG SAFE ALT 100 NM 9900

ELEV	73	D	TDZE	73
			Rwy 12 ldg 8501'	
			Rwy 30 ldg 8501'	



HIRL Rwy 12-30 **L**
MIRL Rwy 18-36 **L**

KING SALMON, ALASKA

58°41'N-156°39'W

KING SALMON (AKN) (PAKN)

HI-VOR Z or TACAN Z RWY 30