

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Idg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

▼

▲

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH: Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF) 1
------------------------	---	---------------------------------

ELEV 2706		TDZE 2706	
6000 HAYNI		VGSi and RNAV glidepath not coincident (VGSi Angle 3.00/TCH 25).	
*LNAV only		IBOXE 5 NM Holding Pattern	
*1.7 NM to RWY 30		128° 5000	
RWY 30		GP 3.00° TCH 40	
1.7 NM		3.2 NM	
CATEGORY		A	
LPV DA		2956-1 250 (300-1)	
LNAV/VNAV DA		3233-1 527 (600-1 5)	
LNAV MDA		3260-1 554 (600-1) 3260-1 554 (600-1 5)	
CIRCLING		3260-1 554 (600-1) 3460-2 754 (800-2 1/2)	

HETTINGER, NORTH DAKOTA

Amdt 1 26MAY16

46°01'N-102°39'W

HETTINGER/JB LINDQUIST RGNL (HEI)

RNAV (GPS) RWY 30