

HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or ellipses designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
ALAMOGORDO, NM HOLLOMAN AFB (HMN)	HS1 HS2 HS3 HS4 HS5 HS6	Twy R, Twy G, and Twy L have multiple hold lines for Rwy 07-25 and Rwy 04-22. Contact tower if confused or lost. Hold line on Twy /EOR A and Twy/EOR H have multiple POV access roads, possibility of high vehicle traffic. Hold line on Twy /EOR B and Twy C for Rwy 07-25 have multiple POV access roads, possibility of high vehicle traffic. Multiple hold lines at intersecting rwys. Landing/departing aircraft disregard hold lines, taxiing aircraft contact tower prior to crossing hold lines. Multiple hold lines where rwys intersect. Hold line also at Twy D. Contact tower if confused or lost. POV crossing controlled by tower. Hold line located on each side of Rwy 07-25. Possibility of high vehicular traffic.
ALBUQUERQUE, NM ALBUQUERQUE INTL SUNPORT (ABQ)	HS 1 HS 2 HS 3	Runway Incursion Risk. Rwy 08 and Twy E1. Runway Holding Position Markings further from Rwy than expected. Runway Incursion Risk. Rwy 03-21 and Rwy 12-30 and Twy F, C and G. Complex geometry due to converging Rwy and Twys. Wrong Rwy departure risk. Rwy 21 at intersection Twy G. Acft turn in wrong direction for take-off. Runway Incursion Risk. Rwy 03-21, Twy E and Twy H. Runway Holding Position Markings further from the Rwy than expected.
ASPEN, CO ASPEN-PITKIN COUNTY/ SARDY FLD (ASE)	HS 1 HS 2 HS 3	Twy A2. Short taxi distance from ramp to rwy. CAUTION: High t/c intxn - acft rtely hold short of Twy A4 on Twy A when indb to trml or general aviation ramp. Rwy 33 and Twy A9. Non-typical location for rwy holding position marking.
COLORADO SPRINGS, CO CITY OF COLORADO SPRINGS (COS)	HS 1 HS 2 HS 3 HS 4	The apch ends of Rwy 13 and Rwy 17R; and Twy A1. Twy A4 and Twy G at Rwy 17R-35L. Int of Twy E4, Twy G, Twy H and Twy E. Apch ends of Rwy 35R and Rwy 35L.
DENVER, CO CENTENNIAL (APA)	HS 1 HS 2 HS 3 HS 4	Rwy 17L at Twy A1. Twy A, Twy A8, Twy A9 and Twy C1 congested INT. Rwy 10 hold line on Twy C1 is located 30 ft from edge of ramp. Hold Short Line for Rwy 17L-35R on Twy B8.
DENVER, CO DENVER INTL (DEN)	HS 1	Twy ED at Twy M. Close proximity to Rwy 17R apch.

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

HOT SPOTS

(CONTINUED)

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
DENVER, CO ROCKY MOUNTAIN METRO (BJC)	HS 1 HS 2	Pilots taxiing south on Twy D and instructed to cross Rwy 03 mistakenly turn onto Rwy 03. Pilots taxiing on Rwy 03 and instructed to hold short of Rwy 12R/30L fail to hold short. Hold line immediately after turn onto Rwy 03. Multiple hold lines in close proximity. Hold line on Twy B south of Rwy 12R-30L is prior to Twy D.
EAGLE, CO EAGLE COUNTY RGNL (EGE)	HS 1	High density parking area.
GRAND JUNCTION, CO GRAND JUNCTION RGNL (GJT)	HS 1	Rwy 22 and Rwy 29 close proximity, wrong rwy departure risk.
ROSWELL, NM ROSWELL AIR CENTER (ROW)	HS 1	Twy A, Twy B, and Twy D form a complex int in close proximity to Rwy 03-21.

*See appropriate Chart Supplement HOT SPOT table for additional information.