

26022

ILS RWY 24R (CAT II & III)
CLEVELAND-HOPKINS INTL (CLE)

MISSED APPROACH:
Climb to 1700 then
climbing right turn to
3000 direct DJB
VOR/DME and hold.

Ⓐ

127.85




PASLE
CO 39.9
114.4 ACO
Chan 9

MISSED APCH FIX
DRYER
DJB  113.6
Chan 83

LOCALIZER 111.55
I-PVY ::::=
Chan 52(Y)

ELEV	799	D	TDZE	780
------	-----	----------	------	-----



REIL Rwy 10
TDZ/CL Rwy 6L, 6R, 24L and 24R
HIRL Rwys 6L-24R, 6R-24L and 10-28

1700 ↑	3000 ↗	DJB 	VGSI and ILS glidepath not coincident (VGSI Angle 3.00°/TCH 65).	SHERK I-PVY <u>6.5</u>
			GROZA I-PVY <u>3.3</u>	
			2000	3000
			238°	
			2000	
			IM 880	
			1064'	
			3.7 NM	3.2 NM
			GS 3.00° TCH 55	
CATEGORY	A	B	C	D
S-ILS 24R	CAT II RA 100/12 100 DA 880			
S-ILS 24R	CAT III RVR 06			

CATEGORY II & III ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

CLEVELAND-HOPKINS INTL (CLE)

ILS RWY 24R (CAT II & III)

EC-2, 06 AUG 2026 to 03 SEP 2026