

25331

RNAV (RNP) Z RWY 35R
LOUISVILLE MUHAMMAD ALI INTL (SDF)

MISSED APPROACH: Climb to 1600 then climbing right turn to 4000 direct TORAC and hold.

GND CON
121.7 348.6

DZE 479

HIRL all Rwys
TDZL/RCLS Rwys 17L,
17R, 35L and 35R

VGSI and RNAV glidepath not coincident
(VGSI Angle 3.00/TCH 71).
See planview for multiple IF locations.

PARCL

2400
GP 3.00
TCH 60

C
313 (300- $\frac{1}{2}$)
413 (400- $\frac{3}{4}$)

D

AUTHORIZATION REQUIRED

LOUISVILLE MUHAMMAD ALI INTL (SDF)
RNAV (RNP) Z RWY 35R