

KING SALMON, ALASKA

HI-VOR Z or TACAN Z RWY 30

VORTAC AKN <u>112.8</u> Chan 75	APCH CRS 296°	Rwy Idg 8501 TDZE 73 Arpt Elev 73
---	-------------------------	--


[USAF]

KING SALMON (AKN) (PAKN)

DME required.


MISSED APPROACH: Climbing left turn to 3000 on heading 240° and on AKN VORTAC R-210 to OLLER/15 DME and hold.

ATIS 128.8	ANCHORAGE CENTER 124.8 354.0	TOWER ★ 118.3 279.5	GND CON 121.9	CTAF 121.9 0 352.05	UNICOM 122.95
---------------	---------------------------------	------------------------	------------------	------------------------	------------------



EMERG SAFE ALT 100 NM 9900

ELEV	73	D	TDZE	73
------	----	----------	------	----



CATEGORY	C	D	E
S-30	480-1½	407	(500-1½)
CIRCLING	580-1½ 507 (600-1½)	900-2¾ 827 (900-2¾)	960-3 887 (960-3)

KING SALMON, ALASKA

58°41'N-156°39'W

KING SALMON (AKN) (PAKN)

Amdt 6 03NOV22

HI-VOR Z or TACAN Z RWY 30

AK, 09 JUL 2026 to 03 SEP 2026