

LOC I-LCK
110.1

APP CRS
232°

Rwy Ldg
23L
23R
TDZE
740 743
Apt Elev
744 744

ILS or LOC RWY 23L
RICKENBACKER INTL (LCK)

⚠ Circling NA northwest of Rwy 5L-23R. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting: increase DA to 975 feet; increase all MDAs 40 feet and S-LOC 23L visibility Cats C/D to RVR 5500 and Circling visibility Cat D to 2¼ SM. Autopilot coupled approach NA below 1000 MSL.

MALSR

MISSED APPROACH: Climb to 3000, then left turn direct XUB VOR and hold.

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------

ALTERNATE MISSED APCH FIX

PICKL
376 LC

RADAR REQUIRED

LOM/IAF
PICKL
376 LC
RADAR

MSA LC 25 NM

3100

MISSED APCH FIX
YELLOW BUD
XUB
112.5

ELEV **744** TDZE **23L 740**
TDZE **23R 743**

TDZL/RCLS Rwy 5R
REIL Rwy 23R
HIRL Rwys 5L-23R and 5R-23L

FAF to MAP 4.9 NM

Knots	60	90	120	150	180
Min:Sec	4:54	3:16	2:27	1:58	1:38

3000

XUB

LC LOM RADAR

2372

052°

2900

232°

2400

GS 3.00°
TCH 62

4.9 NM

Remain within 10 NM

VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 78).

CATEGORY	A	B	C	D
S-ILS 23L	940/24 200 (200-½)			
S-LOC 23L	1 220/24 480 (500-½)		1 220/50 480 (500-1)	
SIDESTEP RWY 23R	1 220-1 477 (500-1)		1 220-1½ 477 (500-1½)	1 220-2 477 (500-2)
CIRCLING	1 240-1 496 (500-1)		1 280-1½ 536 (600-1½)	1 400-2 656 (700-2)

EC-2, 06 AUG 2026 to 03 SEP 2026

EC-2, 06 AUG 2026 to 03 SEP 2026