

TACAN RWY 32

TACAN BKF
Chan 33

APCH CRS
328°

Rwy ldg 11,006
TDZE 5663
Arpt Elev 5663

[USAF]

BUCKLEY SFB (KBKF)

⚠ * When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile,
CAT CDE vis to 1¾ miles.
** Circling not authorized east of Rwy 14-32.

ALS-F1
A1

MISSED APPROACH: Climbing right turn to 8200
and intercept BKF TACAN R-148 direct BEKEE
and hold or as directed by ATC.

ATIS ★
119.675 259.3

DENVER APP CON
128.45 251.075

TOWER ★
121.0 291.675

GND CON
121.6 275.8

CAT E remain within 4.25 NM of rwy when circling.

Missed approach requires use of RNAV or ATC RADAR monitoring.

ELEV 5663

TDZE 5663

8200

BEKEE
BKF 13

BKF TACAN

CENAR
BKF 1.7

BKF 3

LASTE
BKF 4

MUSOE
BKF 6.5
RADAR

BEKEE
BKF 13

DERYL
BKF 16

0.5 NM

2.3 NM

2.5 NM

CATEGORY

A

B

C

D

E

S-32 *

6280/24 617 (700-½)

6280-1⅓ 617 (700-1⅓)

CIRCLING**

6280-1 617 (700-1)

6360-2 697 (700-2)

6400-2¼ 737 (800-2¼)

6420-2¾ 757 (800-2¾)

HIRL Rwy 14-32

REIL Rwy 14

TACAN RWY 32

SW-1, 03 SEP 2026 to 01 OCT 2026

SW-1, 03 SEP 2026 to 01 OCT 2026