

LOC I-STX
109.5

APP CRS
097°

Rwy Ldg
TDZE **74**
Apt Elev **74**

ILS or LOC RWY 10
HENRY E ROHLSEN (STX)(TISX)

▼

▲

Circling NA N of Rwy 10-28. If local altimeter setting not received, procedure NA. For inoperative MALSR, increase S-ILS 10 all Cats visibility to 1.

MALSR

MISSED APPROACH: Climb to 700 then climbing left turn to 2400 direct COY VOR/DME and hold, continue climb-in-hold to 2400.

ATIS
135.65

SAN JUAN CENTER
128.65 279.6

ST. CROIX TOWER ★
118.6 (CTAF) 239.3

GND CON
121.7

UNICOM
123.0

ADF REQUIRED

VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 73).

Remain within 10 NM

ST LOM 2400

2000

1404

1500

GS 3.00° TCH 59

4 NM

ELEV 74	D	TDZE 74
REIL Rwy 28 HIRL Rwy 10-28		
FAF to MAP 4 NM		
Knots	60	90 120 150 180
Min:Sec	4:00	2:40 2:00 1:36 1:20

CHRISTIANSTED, ST. CROIX, VIRGIN ISLANDS

Amdt 7C 20MAY21

17°42'N-64°48'W

HENRY E ROHLSEN (STX)(TISX)

ILS or LOC RWY 10