



Federal Aviation Administration

SAFETY ALERT

Date: November 25, 2015

To: Users of the U.S. Terminal Procedures Publication (TPP) and digital-Terminal Procedures Publication (d-TPP)

From: Aeronautical Information Services

Subject: TPP Volume SC1 missing Page L20 and d-TPP missing the following Takeoff Procedures from SC1TO.PDF file:

Watonga, OK, Watonga RGNL (JWG); Weatherford, OK, Thomas P. Stafford (OJA); West Memphis, AR, West Memphis Muni (AWM); and Woodward, OK, West Woodward (WWR)

Terminal Procedure Publication, volume SC1, effective 12/10/15, page L20 missing. Four separate airport takeoff procedures not worked for the cycle were inadvertently omitted from the SC1TO.pdf file for the 1513 d-TPP and the DDTPPD_201513.zip file.

You may download the correct file for the SC1 volume TAKEOFF MINIMUMS, (OBSTACLE) DEPARTURE PROCEDURES, AND DIVERSE VECTOR AREA (RADAR VECTORS) for Watonga, OK, Watonga RGNL (JWG), Weatherford, OK, Thomas P. Stafford (OJA), West Memphis, AR, West Memphis Muni (AWM), and Woodward, OK, West Woodward (WWR) at <http://aeronav.faa.gov/d-tp/1513/SC1TO.PDF>. A replacement DDTPPD_201513.zip file has been uploaded to all FTP folders.