



Federal Aviation Administration

SAFETY ALERT


Date: November 25, 2015

To: Users of the U.S. Terminal Procedures Publication (TPP) and digital-Terminal Procedures Publication (d-TPP)

From: Aeronautical Information Services

Subject: TPP NW1 volume Page 797, Airport Diagram at Sidney, MT, Sidney-Richland Muni (SDY), missing taxiways and apron area

Airport Diagram at Sidney, MT, Sidney-Richland Muni (SDY), Terminal Procedures Publication, volume NW1, effective 12/10/15, page 797, is missing taxiways and apron area. Below is a snapshot of the corrected portion of the chart:



You may download the correct airport diagram file at (SDY) for the NW1 volume, page 797, at <http://aeronav.faa.gov/d-tp/1513/05303AD.PDF>. A replacement DDTPPC_201513.zip file, including the replacement file, has been uploaded to all FTP folders.