



U.S. Department
of Transportation
**Federal Aviation
Administration**

March 24, 2010

Ing. Abel Enrique Gontero
Director, Dirección de Certificación Aeronáutica
ANAC- DNA
Ave. Fuerza Aérea Km 5 ½
Pabellón 110- Lockheed
CPX 5010JMN- Córdoba
Argentina

Dear Mr. Gontero:

On October 16, 2009, the Federal Aviation Administration revised Title 14 of the Code of Federal Regulations (14 CFR) parts 1, 21, and 45. Portions of this new rule become effective on April 14, 2010. A significant change resulting from this new rule is that aircraft engines and propellers will no longer be exported using FAA Form 8130-4, Export Certificate of Airworthiness. Instead, aircraft engines and propellers will be exported using FAA Form 8130-3, Authorized Release Certificate. Complete aircraft will continue to be exported using FAA Form 8130-4.

This information is being sent as prescribed in Chapter 5 paragraph 52 of the bilateral airworthiness agreement existing between our two countries.

Please provide your acknowledgement of this change to our regulations. We look forward to your reply.

Sincerely,

A handwritten signature in black ink, appearing to read "Chris Carter".

Chris Carter
Manager, International Policy Office
Aircraft Certification Service