

UNAPPROVED PARTS NOTIFICATION

Aircraft Certification Service



FAA
Aviation Safety

No: 2016-20110831001 (**Rescinded Oct. 26, 2016**)

Date: June 20, 2016

<http://www.faa.gov/aircraft/safety/programs/sups/upn>

BACKGROUND

On March 2, 2016 the Bilateral Oversight Board (BOB) decision 006 was signed which provided for ETSO acceptance as outlined in Technical Implementation Procedures for Airworthiness and Environmental Certification between the FAA and EASA, Revision 5. The ETSO/TSO acceptance process specifies that the importing authority accept the exporting authority's TSO or ETSO authorization and need not issue its own corresponding approval.

Based on the information above, this notice serves to rescind the original UPN No: 2016-20110831001, dated June 20, 2016.

AFFECTED PRODUCTS

Model	Part Number	Description
Nebulon	AVE-WPR-51G-401	Wingtip navigation red LED light
Nebulon	AVE-WPG-51G-401	Wingtip navigation green LED light
Pegatron	AVE-POSW-74G-401	Tail/rudder position LED light
Red Baron XP (Aurora E-Series)	unknown	Anti-collision red LED light
Red Baron XP (Aurora E-Series)	unknown	Anti-collision white LED light
SmartStrobe	AVE-IS30ANCSAS-02G	Wingtip Anti-collision strobe LED light

Additionally, the FAA notes that the Red Baron XP (Aurora E-series) anti-collision lights should not have been subject to the UPN. Although not ETSO certified, these lights were not intended for installation on type certificated aircraft.

FURTHER INFORMATION

This notice originated from the FAA Farmingdale MIDO, 7150 Republic Airport, Suite 236, Farmingdale, NY 11735, Telephone (631) 694-8420, Fax (631) 694-8424.