

Federal Aviation Administration

Memorandum

Date:	JUL 18 2017
To:	Al Spence, Directives Program Manager, ASP-110 John S. Duncan, Director, Flight Standards Service, AFS-1 DM Barly 100
From:	John S. Duncan, Director, Flight Standards Service, AFS-100M
Prepared by:	Richard Mathews, Directive Management Officer, AFS 140 702 DMA
Subject:	Cancellation of Advisory Circular AC 90-58C

Flight Standards Service is requesting the cancellation of AC 90-58C, VOR Course Errors Resulting from 50 kHz Channel Misselection. The advisory information in this AC is based on technology that is no longer in use. The main issue was with certain types of 200 channel airborne receivers when the receiver was inadvertently mistuned 50 kHz from frequency of a 100 kHz VOR ground station. This is no longer relevant.

AC Number	Date	Document Title	OPR	Reason for Cancellation
AC 90-58C	4/7/1975	VOR Course Errors Resulting from 50 kHz Channel Misselection	AFS-300	AC based on technology no longer in use

Should you have any concerns or questions, please contact Mr. Richard Mathews, AFS-140, at (202) 267-4166.